

FIG. 1





FIGURE 2







FIGURE 3






FIGURE 5

CONSUMABLE COMPONENT	AVERAGE/ PREDICTED LIFE	REPAIR COST ESTIMATE	REPLACEMENT ESTIMATE	AVAILABILITY	DELIVERY TIME
LASER TUBE	5 YRS	20 HRS	\$15,000.00	Y	3 DAYS
TUBE WINDOWS	5 YRS	15 HRS	\$20,000.00	Y	1 DAY
FRONT OPTICS MODULE	5 YRS	15 HRS	\$55,000.00	N	N/A
REAR OPTICS MODULE	5 YRS	20 HRS	\$45,000.00	Y	1 DAY
MONITOR OPTICS MODULE	110x10 ⁹ PULSES	5 HRS	\$30,000.00	Y	1 DAY
HALOGENED FILTER	110x10 ⁹ PULSES	1 HR	\$1,000.00	Y	2 DAYS

FIGURE 6

FIG. 2297850

FIG. 710	FIG. 720	FIG. 730	FIG. 740	FIG. 750
Payment Due Date	Installment Amount U.S. \$	% of Total Balance	Estimated Used False Count	Actual Used False Count
761 J. - X	20,000.00	10	114 x 10 ⁶	130 x 10 ⁶
762 X + 3 mos.	30,000.00	25	114 x 10 ⁶	110 x 10 ⁶
763 X + 6 mos.	30,000.00	40	114 x 10 ⁶	108 x 10 ⁶
764 X + 9 mos.	30,000.00	55	114 x 10 ⁶	85 x 10 ⁶
765 X + 12 mos.	30,000.00	70	114 x 10 ⁶	150 x 10 ⁶
766 X + 15 mos.	30,000.00	85	114 x 10 ⁶	132 x 10 ⁶
767 X + 18 mos.	30,000.00	100	114 x 10 ⁶	80 x 10 ⁶

FIG. 7

CUSTOMER	ID	BILLING ADDRESS	DELIVERY ADDRESS	PAYMENT HISTORY	ACCOUNT STATUS
471	COMPANY A AX1	200 HARBOUR DR. VANCOUVER, BC CANADA	SEE BILLING ADDRESS	NO DEFAULTS	CURRENT
472	COMPANY B BX1	150 MITCHELL ST. SANTA CLARA, CA U.S.A.	SEE BILLING ADDRESS	NO DEFAULTS	CURRENT
473	COMPANY C CX2	1 QUEEN'S PARK SINGAPORE	200 INDUSTRIAL WAY, SINGAPORE	TWO DEFAULTS	DEFAULT
474	COMPANY D DX1	10 BERNAL ST. WILMINGTON, MA U.S.A.	600 HIGHLAND PARK, SAN JOSE, CA, U.S.A.	ONE DEFAULT	CURRENT
475	COMPANY E EX2	45 RUE RIVOLI MONTREUIL, FRANCE	SEE BILLING ADDRESS	NO DEFAULTS	CURRENT

400

FIGURE 8